

Mitutoyo

METROLOGY HANDBOOK

The science of measurement

UK 2ND EDITION

Second Edition

Written by Nobuo Suga and Peter Rollings

Contents

to the Second Edition	012
his book	014
Fundamentals	
01 // Introduction	017
<i>In search of a constant</i>	018
<i>Birth of a standard: the Egyptian cubit</i>	020
<i>Platinum, iridium and the prototype metre</i>	021
<i>The helium-neon laser interferometer</i>	022
<i>Calibrating longer lengths</i>	023
<i>Traceability to national standards</i>	024
<i>Accuracy and uncertainty</i>	025
<i>Traceability of length on the global scale</i>	026
<i>Length defined by time</i>	027
<i>Length defined by temperature</i>	028
<i>End standards</i>	030
<i>Line standards</i>	032
<i>Summary</i>	033
02 // Units on engineering drawings	035
<i>Introduction to metric units</i>	036
<i>Introduction to inch units</i>	037
<i>Representing dimensions</i>	038
<i>Tolerancing dimensions</i>	039
<i>Relevant SI units</i>	040
<i>The pyramid of accuracy</i>	041
<i>The SWIPE principle</i>	042
Metrological concepts	
03 // Geometric dimensioning and tolerancing (GD&T)	045
<i>The language of GD&T</i>	046
<i>GD&T symbols</i>	047
<i>Form controlled by size</i>	048
<i>Form independent of size</i>	049
<i>The MMR bonus tolerance</i>	050
<i>An example of MMR bonus</i>	051
<i>Tolerance zones and the start of GD&T</i>	052
<i>Size and Form tolerancing</i>	053
<i>Variation of Size and Form</i>	054
<i>Straightness</i>	055
<i>Measuring Straightness</i>	056
<i>Flatness and Parallelism</i>	057
<i>Measuring Flatness</i>	058

<i>Measuring Flatness by CMM</i>	059
<i>Measuring Parallelism by CMM</i>	060
<i>Roundness</i>	061
<i>Cylindricity</i>	063
<i>Cylindricity measurement – spiral tracing</i>	064
<i>Cylindricity measurement – slicing</i>	065
<i>Profiles of lines and surfaces</i>	066
<i>Measuring a line profile</i>	067
<i>Perpendicularity</i>	068
<i>Angularity</i>	070
<i>Position</i>	071
<i>Zero positional tolerance under MMC</i>	073
<i>Concentricity</i>	074
<i>Symmetry</i>	075
<i>Circular and Total Runout</i>	076
<i>Checking Runout</i>	077
<i>GD&T in action</i>	078
Chapter 04 // Measurement basics	079
<i>Gauge repeatability and reproducibility (GR&R)</i>	080
<i>The averaging method of finding GR&R</i>	080
<i>The range method of finding GR&R</i>	082
<i>Choosing the correct tool</i>	083
<i>Abbe's principle</i>	084
Chapter 05 // Surface texture	085
<i>Principles of surface roughness measurement</i>	086
<i>Isolating the roughness data</i>	087
<i>Selecting the correct λ_c</i>	088
<i>Sampling length</i>	089
<i>Sampling length considerations</i>	090
<i>Stylus tip geometry and measuring force</i>	091
<i>Hardcopy and the aspect ratio</i>	093
<i>Surface roughness comparators</i>	094
<i>Surface roughness testers</i>	096
<i>Skidded and skidless detectors</i>	097
<i>Using dedicated fixtures for better GR&R</i>	098
<i>Peak and valley parameters R_t and R_z</i>	099
<i>Four common roughness parameters</i>	100
<i>A tale of two parameters, R_{3z} and $R_z(JIS)$</i>	101
<i>Dimensioning surface roughness</i>	103
<i>Surface texture symbols</i>	104
<i>The 16% and Max rules</i>	105

Testing a lubricating surface	106
Transverse tracing	108
To skid, or not to skid... ..	109
Testing gear teeth	110
Testing difficult surfaces	111
Chapter 06 // Hardness testing	113
Usefulness of hardness testing	114
Indentation test force	115
Hardness testing with a ball indenter	116
Effect of ball indenter material	117
Brinell hardness testing	118
Rockwell hardness testing	119
Rockwell scales and the indenter	120
The Rockwell test cycle	121
Testing curved surfaces	122
Choosing the best Rockwell scale	123
Vickers and Knoop	125
The advantage of the Knoop indenter	126
Measuring the Vickers indentation	127
Automatic Vickers hardness testing	128
Hardness testing very small specimens	129
Testing case hardening depth	130
Instrumented indentation testing	131
Standard reference material (SRM)	132
Testing soft materials	134
Chapter 07 // Granite surface plates	137
Main features	138
Concavity and convexity	139
Hand finished flatness	140
Calibrating flatness	141
Types of granite and accuracy grades	142
Chapter 08 // Gauge blocks	143
The combination gauge block set	144
Size and tolerance ratios	145
Johansson's GO/NO GO gauges	146
The inch and the millimetre	146
Rectangular or square?	147
Ceramic gauge blocks (ZrO ₂)	148
Rectangular long blocks	149
A gauge block unaffected by temperature	150

Measurement standards

A gauge block with a calibrated expansion coefficient	151
The future	152
Gauge block accessories	153
Testing gauge blocks with optical flats	154
Building up a stack	155
2 mm-base gauge blocks	156
The phenomenon of wringing	157
How to wring gauge blocks	158
Wringing strategies	159
Wringing film thickness variation	160
Recalibration	161
Standard temperature for length measurement	163
Worn, rusty, and painted gauge blocks	164
Storing and cleaning gauge blocks	165
Round robin proficiency test	166
Gauge calibration / gauge retrieval software	167

Chapter 09 // GO/NO GO gauging

Plug gauges	170
The two-finger method of gauging	172
Testing for function	174
Ball gauges	175
GO gauges and the MMC	176
Ring gauges and setting rings	177
Calibrating ring gauges and setting rings	178
Thread ring gauges	179
NO GO ring and thread ring gauges	180
Thread plug gauges	181
Screw threads	182
Tooling balls	183
Flush pin gauges	184
Threaded flush pin gauges	185
Laser scan micrometers	186
Caliper type GO/NO GO gauges	188
Telescopic gauges	189

04 Small tools

Chapter 10 // Micrometers

The first micrometer	194
Birth of the modern micrometer	195
The parts of a typical micrometer	196
Early stages of micrometer development	198
Micrometer threads	199

How to read a metric micrometer	200
How to read an inch micrometer	201
The digital micrometer	202
Cleaning the measuring faces	204
Setting the zero (or reference) point	205
Testing parallelism of measuring faces	206
The 4 to 1 rule	208
The 5-step calibration method	209
Measuring wall thickness	210
Blade and groove micrometers	212
The disc micrometer	213
60° V-anvil micrometer	214
Spline and point micrometers	215
Inside caliper micrometer	216
Depth micrometers	217
Measuring internal diameters	220
Small hole gauges	221
Bore measurement	222
Inside micrometers	224
Micrometer heads	225
Wireless data transfer and fast operation	226
Micrometers as data gathering devices	227
Chapter 11 // Calipers and the vernier scale	229
Vernier calipers	230
Angle readings with the vernier scale	232
Vernier height gauges	233
Parallax error	233
Dial calipers	234
Tungsten carbide jaws	234
The ABSOLUTE caliper	235
Measuring technique	236
Measuring force and position in the jaws	238
Step and depth measurements	239
Measuring hole diameters	240
Measuring narrow grooves	241
Checking outside jaws	241
Caliper calibration	242
Coolant proof digital calipers	244
Special jaws for special purposes	245
Jaw attachments	246
Caliper accuracy	247

Chapter 12 // Indicators	249
Early examples	250
Indicator specifications	251
Multi revolution dial indicators	252
Single revolution dial indicators	253
Measuring force	254
Choosing a suitable indicator	255
Indicator calibration	256
ABSOLUTE digital indicators	257
Lever indicators	258
Plunger versus lever indicators	259
How to use lever indicators	260
Lever indicators and the cosine effect	261
Checking runout and diameter	262
Indicator stands	264
Hysteresis	265
Inductive probe heads and linear gauges	266
Bore gauge indicators	268
05 Large instruments	
Chapter 13 // Profile projectors	273
Contour illumination	274
Surface illumination	275
A mirror image	276
Measuring angles	277
Overlay charts	278
Edge detection and repeatability	281
Geometric analysis on profile projectors	283
Chapter 14 // Microscopes	285
The stereo microscope: easy viewing in 3D	286
The toolmaker's microscope: a jack of all trades	287
The measuring microscope: high-magnification versatility	288
High-performance optics	290
Chapter 15 // Profile and contour tracing	291
Contour tracers	292
Measuring V-pulley contours	294
Measuring internal form with a dual stylus	296
Measuring splined bores	297
Relating internal to external form	298
Contracer calibration and compensation	299
Chapter 16 // Vision measuring systems	301
Software control	302

Contents

High magnification digital imaging	303
Edge detection tools	304
Interferometric measurement of small heights	305
Frozen motion means non-stop measurement	306
Vision system measurement analysis	307
Fast measurement and an audit trail	308
Chapter 17 // Coordinate measuring machines	309
The first commercial CMM	310
The first probes	311
Cartesian coordinates	312
Machine and Part Coordinate Systems	313
Polar coordinates	314
The moving bridge CMM	315
Computer Numerical Control	316
Air bearings and kinematically true motion	317
Software and training	319
Probe qualification	320
An agile CMM	321
A production line CMM	322
An extreme CMM	323
Maximum Permissible Error	325
Measuring strategies	326
CMM software	327
Measuring gears	328
Bevel gears	329
Spur gears	330
Worms and worm wheels	331
Measuring aerofoils	332
CMM simulation	333
Model Based Definition	334
Automatic part-program generation	335
Reverse engineering	336
Clamping kits	337
The ball bar	338
A calibration artefact with negligible CTE	339
CMM performance specification-standard overview	340
The ISO 10360 standards	341
ISO 10360-2/5 testing	342
Temperature compensation and ISO 10360	345
How many points?	346
Locating threaded holes	347

Measuring keyways	348
Measuring profiles	349
Evaluating surfaces	350
Projections and projected planes	351
Service and verification	352
Summary	353
Chapter 18 // Probes	355
Touch trigger probes	356
Analogue probes	357
The probe head	358
TP20 and TP200 probes	359
MPP-310Q analogue scanning probe	361
REVO analogue scanning probe	362
Line laser scanning probe	363
Surface roughness probe	364
Ultrasonic Micro Accurate Probe (UMAP)	365
Autochanging probes and styli	366
06 Limits of measurement	
Chapter 19 // High accuracy calibration	369
Linear scales and encoders	370
CMM reference spheres	371
Roundness reference standards	372
Step gauges	373
Gauge blocks	374
Ring gauges and setting rings	375
Chapter 20 // Measuring machines today	377
The CMM	378
Single-axis measuring machine	380
The VMM	383
Roundness testers	384
Contour tracers	385
Form tracers	386
Surface texture testers	387
Glossary	388
Index	390
Acknowledgements	396
Mitutoyo (UK) locations	397